YEARLY RELIABILITY REPORT

A snapshot of GRU's reliability for fiscal year 2020 (October 2019-September 2020)

METER READ ACCURACY 99.95%

Energy Delivery

- >> 1,449 miles

 OF ELECTRIC LINES
- » 99.99% ELECTRIC AVAILABILITY



Natural Gas

>> 810 milesOF GAS LINES




No Line Locate Requested: 47%

NW 58 NE 8

SW SE 27 8

DAMAGED GAS LINES BY REGION



Leading cause: Fence Installation - 25%

Water/Wastewater

» 1,183 miles of water lines

6 6 BILLION

GALLONS OF WATER REUSED

» 854 miles of wastewater lines

♦ 8 BILLION

GALLONS OF WATER DELIVERED TO CUSTOMERS



Customer Service



32,513LOBBY TRANSACTIONS

» 403,053

CALL CENTER

72,251

